

Under Review Notification

Raised By: Steven Drouin

Product #: D350-689

Date: 19-03-07

Product Name: Dual High back Seat Installation

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
D350-689-015	IIN-D350-689 Rev. D	Y	Y	N	Y	N	N	Y	19-626	CHG#001
D3059-1	D3059 Rev. A1	Y	Y	N	Y	N	N	Y	19-626	Drawing Update

Description of Issue:
 - Revise drawing D3059 to Rev. B to specify 4130N with minimum M14 tensile strength of 90 ksi

For more Information please see Engineering.

Distribution:	VP Operations	Director of Engineering	Customer Support Manager	Technical Support
	Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
	Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
	QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene